

Ejemplo de ranurado y roscado interior

<https://www.programacioncnc.es/ejemplo-de-ranurado-y-roscado-con-mecanizado-interior/>

```
G54
G92 S1800
G95 G96 F0.2 S160 M4
G0 Z150
T1 D1
G0 X90 Z20
G1 X78 Z5
G1 Z-36
G1 X85
G0 Z0
G1 X-0.4
G1 Z5
G0 G42 X70 Z1
G1 X80 Z-4
G0 G40 X90 Z170
G94 G97 F90 S600 M3
T6 D6
G0 X0 Z10
G83 X0 Z1 I59.773 B13 D2 K1 H0 C1
G0 Z150 X100
G95 G96 F0.2 S120 M4
T2 D2
G0 X16 Z5
G68 X64.35 Z0 C1 L0.5 S100 E110
G0 G41 X65.35 Z0.5
N100 G1 G5 X58.35 Z-3
G1 G36 R13 X58.35 Z-32
G1 G36 R6 X25.402 Z-54
N110 G1 X18 Z-54
G0 G40 G7 Z150
G95 G96 F0.08 S50 M4
T10 D10
G0 G41 X40 Z-15
G88 X60 Z-19 Q62 R-25 K5 D-2
G0 Z150
G95 G96 F0.15 S60 M4
T10 D10
G0 X40 Z1.5
G86 X58.35 Z0 Q58.35 R-21 I-0.8 B0.4 D-2 L0 C1.5 J0 A29.5
G0 Z150
M30
```

